

Display Logger



Specifications

Accessories



A060 - Serial Download Cable
Serial Download Cable - length 6 feet (2m)



A170 - USB Adapter
Serial to USB Adapter



A203 - Temperature Probe
6" (15cm) High Temperature Immersion Probe



D605 - Piercing Probe
4" (10cm) Thermocouple Handled Piercing Probe

Accessories



R007 - 9V Battery
9V Battery



R157 - AC Adapter
AC Adapter



SW400 - Calibration Software
Logger Calibration Software



SW701 - Software Upgrade
DicksonWare Software Upgrade